
# **SOLDERING KIT CHRISTMAS TREE**



#### **Necessary tools:**

Wire Cutters: we recommend <u>PGC-TR25</u> they are sharp and light

Twizzers: we recommend <u>PGC-00SA</u>

Soldering iron: <u>CHN-SLD802</u> is budged solution, <u>SLD-FAST-75W</u> is professional solution


Soldering wire: we recommend <u>Solder-Wire-SAC0307-0-8</u>

### **General tips for soldering:**

1. Switch On the soldering iron, setup the working temperature to 350 C. Wait until the Soldering Iron reach this temperature – there is LED indicator which will pulse when the temperature is reach.

- 2. Before soldering clean the Soldering tip with wet sponge from the black resedues.
- 3. Never touch the heated soldering tip or body.
- 4. Do not leave the Soldering Iron unattended.
- 5. Be careful to not touch cables, table, cloths with the soldering iron heated body or tip.
- 6. Place the electronic component on it's place, watch out if there is polarity.
- 7. Touch the component pad which you want to solder and wait 3-4 seconds to heat up.
- 8. Feed a little from the soldering wire until the component lead is flooded with tin and it's shinny and glossy.
- 9. If the soldering is not shinny but dull please re-solder with colophony.

# **SLD-KIT-XMASTREE Schematic:**



### **Assembly instructions:**

#### List of Components:

R1, R3, R5	4.7 K ohm	3+3 pcs	
R2, R4, R6, R7	100 ohm	4+4 pcs	
D1,D2,D3,D4,D5,D6,D19	red LED	7+7 pcs	with polarity!
D7,D8,D9,D10,D11,D12	green LED	6+6 pcs	with polarity!
D13,D14,D15,D16,D17,D18	yellow LED	) 6+6 pcs	with polarity!
Q1,Q2,Q3	NPN	3+3 pcs	with polarity!
C1,C2,C3	47uF	3+3 pcs	with polarity!
USB connector		1 pce	
SWITCH		1 pce	

Follow this sequence of soldering:

- 1. Solder all resistors to their places
- 2. Solder the red, green and yellow LEDs to their places, The longer led should be inserted in the square PCB pad.
- 3. Solder the transistor follow the shape on the PCB, do not place with mirror!
- 4. Solder the capacitors the shorter leg go to the white filled pad.
- 5. Solder the USB and SWICH to the base PCB
- 6. Insert and solder the two tree PCBs to the base pay attention to + marking!